

## Chute Savane

Inspection of a water intake gantry crane

**Client**           ⇒   **Alcan**  
**Location**       ⇒   **Lac St-Jean**  
**Year**            ⇒   **2003-2004**



- Gantry crane inspection and evaluation

- Mechanical and structural evaluation of an overload lifting

